

**METHOD STATEMENT
FOR WORK STATION 6
GLAZING BEADS**

LOCATION:	ACE WINDOWS NE	COMPLETED BY:	R. PYNE
DATE:	17/5/2016		

TASK GLAZING BEADS	KEY POINT
ENSURE ELECTRICITY SUPPLY IS ISOLATED	
ENSURE THE AREA TIDY AND FREE FROM SWARF	
ENSURE THE OPERATOR WEARS PPE (EAR PROECTION AND SAFETY GLASSES)	
ENSURE ELECTRICITY SUPPLY IS TURNED ON	
CHECK EMERGENCY STOP BUTTON WORKS	
START MACHINE	
PLACE BEAD IN MACHINE	
OPERATE THE CLAMP	
NOTE ; HANDS ARE FREE FROM MACHINE	
NOTE: ENSURE OPERATOR IS CAPABLE AND COMPETENT AND HAS FECIVED INFORMATION INSTRUCTION AND TRAINING	
ENSURE MANAFACTURES INSTRUCTIONS ARE FOLLOWED	